

303 R 0.500"

Work Order ID 73834

Friday, September 16, 2011 11:44:48 AM



Page 1

Item ID: D2652

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 9/16/2011 Start Qty: 600.00



Cust Item ID:

Required Date: 10/7/2011 Req'd Qty: 600.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D2652

Rev A

100

0.00



Hardinge CNC LATHE SMALL

Hardinge

Memo

0.00

Hardinge CNC Lathe Small

1-TURN AS PER FOLIO FA252 & DWG D2652 □ FOLIO
REV: W/A □ DWG REV: A □ 2-DEBURR AS REQUIRED600 ϕ W/A 11/11/21

110

0.00



QC2- Inspect parts off machine FAI/FAIB

QC

Memo

0.00

Quality Control

600 ϕ W/A 11/11/21

120

0.00



QC8- Inspect parts - second check

QC

Memo

0.00

Quality Control

W/A 11/11/22600 ϕ

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73834

Friday, September 16, 2011 11:44:48 AM



Page 2

Item ID: D2652

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 9/16/2011 Start Qty: 600.00



Cust Item ID:

Required Date: 10/7/2011 Req'd Qty: 600.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 Packaging Packaging	Identify as per dwg & Stock Location <u>019</u> Memo	0.00 0.00							
140 QC Quality Control	QC21- Final Inspection - Work Order Release Memo	0.00 0.00							

11/11/22 (600)

11/11/22

mf
11-11-22

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, September 16, 2011 11:44:45 AM

Page 1

Work Order ID: 73834

Parent Item: D2652

Parent Item Name: Bushing




Start Date: 9/16/2011

Required Date: 10/7/2011

Start Qty: 600.00

Required Qty: 600.00

Comments: IPP Rev:B 02.06.13 Now machined in house. NG

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M303R0.500  303 Round Bar 0.500"		Purchased	No			100	f	35.9300	0.055	34.73684			

Handwritten: 36.000 27 of 11/11/21

Location

Loc Qty

Loc Code

MAT028

35.93

117143

11.34

118271

11.9

118509

12.69

119661

36.000

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D2652	REV. A SHEET 1 OF 1
DATE 97:03:25		TITLE BUSHING	SCALE 1:1

RELEASED
97/04/25 DS



MATERIAL: AISI 303 SS
NOTE: BREAK ALL SHARP CORNERS 0.010 MAX
TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED